# Oil Field Environmental Incident Summary

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: ANTELOPE-DEVONIAN UNIT 10

Field Name: ANTELOPE Well File #: 1262

Date Incident: 8/21/2016 Time Incident: 16:30 Facility ID Number:

County: MCKENZIE Twp: 152 Rng: 94 Sec: 6 Qtr: SW NW

Location Description:

Submitted By: Alberto Yates Received By:

Contact Person: Troy Brunsell

1501 MCKINNEY

HOUSTON, TX 77010

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:1.4 MileDistance Nearest Water Well:1.4 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

**Brine** 

Other 130 Barrels 125 Barrels 130 barrels

**Description of Other Released Contaminant:** 

Regular water treated with known Oxygen and Scale inhibitors

Inspected: Written Report Received: 10/19/2016 Clean Up Concluded: 9/29/2016

Risk Evaluation:

There is no immediate risk to report at this time. NO OFFSITE IMPACTS

Areal Extent:

25' area offsite south of the location

## Potential Environmental Impacts:

There are no potential environmental impacts to report at this time. All impacts REMAINED ON SITE. No Sensitive areas were impacted due to the incident.

#### Action Taken or Planned:

Upon discovery of the release, two 50 bbl vacuum trucks were dispatched to recover as much of the released regular water as practicable. The majority of the release was contained within the berm (estimated 125 bbls), with approximately 5 bbls going outside of the berm off location (about 25' off location to the south). The remaining impacted material will be cleaned up during the remediation process. Arrangements were made for the impacted material to be cleaned up and disposed of to an approved waste facility.

Wastes Disposal Location: The recovered waste will be taken to an approved waste disposal facility.

Agencies Involved:

# **Updates**

Date: 8/22/2016 Status: Reviewed - Follow-up Required Author: Schiermeister, Robin

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release was not contained; further follow-up is required.

Date: 8/29/2016 Status: Inspection Author: O'Gorman, Brian

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

Arrived on location at 10:45. 61 degrees F, mostly sunny, northwest wind 10-20 mph. Observed the site and took photos. It appeared that the release occurred west of the pumpjack, near a small shed. Excavation of the soils had occurred, with the piping being removed and the hole left open. Approximate size of the excavation was an 8-foot diameter hole approximately 5 feet deep. Vegetation around the perimeter of the release appeared healthy with no salt or petroleum impacts. However, it appeared that the excavated soil had been dumped off the southeast portion of the pad onto pastureland in use. Approximate area of soil was 30 X 20 feet by 4-12 inches in depth. Phoned company contact and let him know what I observed. More follow-up needed.